



March 2013

MV Maks: leakage from oil fired boiler, defective switches at boiler and fire pump, missing protection cover, etc