

MV EEC Atlantic: broken fire line, deck corroded through, corrosion at seachest, insufficient maintenance on deck, etc.