

MV Reksnes: poor maintenance, corrosion, cracks, missing gear wheel protection, etc.