



March 2009

MV Baltic Wind: Decks corrosion, cracking, damaged hatch cover, broken hinges at watertight door, etc.