



October 2009

MV Galan: hull damage, side scuttles not watertight, fire dampers not closable, unsafe electrical installation, etc.