



Mai 2012

MV Rasim Akar: poor maintenance on deck and in engine room, excessive corrosion on engine room hull plating