



August 2007

MV Evangelia: Excessive exhaust gas leakage in engine room (1) and lack of maintenance on deck (2), broken dampers for cargo hold vents (3, 4)