

MV Burak Bayraktar: poor maintenance deck equipment and fire dampers, wrong stowage of dangerous cargo, etc