

## 4 ALBERT EMBANKMENT LONDON SE1 7SR

Telephone: +44 (0)20 7735 7611 Fax: +44 (0)20 7587 3210

MSC.1/Circ.1120/Corr.1 6 November 2015

## UNIFIED INTERPRETATIONS OF SOLAS CHAPTER II-2, THE FSS CODE, THE FTP CODE AND RELATED FIRE TEST PROCEDURES

## Corrigendum

In the annex, the existing text of the unified interpretation of SOLAS regulation II-2/10.2.2.3.2.2 is amended to read as follows:

"The electrical cables to the emergency fire pump are not to pass through the machinery spaces containing the main fire pumps and their source(s) of power and prime mover(s). They are to be of a fire resistant type, in accordance with IACS Unified Requirement E15 Electrical Services Required to be Operable Under Fire Conditions and Fire Resistant Cables, paragraph 2(a), where they pass through other high fire risk areas."

