



MV Mirvat-I: oil discharged at sea - OWS 15ppm alarm manipulated, filters dirty and not in function, clean water overboard line spoiled with oily residues