



UNITED STATES COAST GUARD

U.S. Department of Homeland Security

MARINE SAFETY ALERT

Inspections and Compliance Directorate

March 20, 2018
Washington, DC

Safety Alert 03-18

Don't Wait! Ensure a Better Fate! **Check your immersion suit zipper seams**

During a recent inspection, U.S. Coast Guard Port State Control examiners discovered a significant flaw involving almost all of a vessel's immersion suits. The examiners noted that the glue used to attach the main zipper to the body of the suit had failed. Failure of the suit at this location will prevent the suit from achieving a watertight seal. Such conditions present serious risk to crewmembers in a survival situation.

Due to the high failure rate discovered during the Coast Guard exam (35 out of 40 suits were defective), the Coast Guard **strongly recommends** that vessel operators **inspect their Immersion Suits for this potential unsafe condition**. Do not wait to discover the problem during a real emergency. As a reminder, any replacement survival suits need to be approved by the vessel's Flag State.



Distributed by the Office of Investigations and Casualty Analysis, Washington DC. Questions may be sent to HQS-PF-fldr-CG-INV@uscg.mil.