



MV Celine-I: unsafe electrical installation on bridge, oil leaks in e/r, lack of maintenance on deck