

MV Liquid Era: windows and sidescuttles not watertight, all washing machines out of order, etc.