

MV Gorgonilla: oil leakages in engine room, heating system for accommodation broken – temp. below 0℃ inside crew accommodation