

MV Laura Schulte: insufficient working safety on deck, watertight flaps not properly closable, window frames wasted