

MV Atlantic Project: Unsafe hatch cover securing (1), corroded vent ducts (2, 3) and unsafe electrical installations (4)