

MV MSC Rebecca: hatch accesses not watertight closable, gas welding equipment and piping wasted, etc.